

Name	Danger, Nick	Year	1985	SO Date	07/27/2000
Home	800-555-1110	Make	BMW	End user	12
Work	800-555-1111	Model	325i	Mileage	89423
Fax		Supt Beg	3RD-EYE	Last Mileage	89423
Other		# Users	Automatic	Advisor	Fred
Email	nick@aol.com	PriorSMS	White	Page #	1 of 1
		Serial #	WBAAV33441FU96471		
		Supt End	2.5 6CYL		

## Job Description

### Car towed in - does not start.

Estimated Hours: 0.00

Troubleshoot no start condition.

**Traced to timing belt failure. (See next line.)**

### Replace timing belt and pulley

Estimated Hours: 1.50

Remove valve cover; & inspect valve train.

Check cam tensioner & replace if needed.

Replace timing belt & pulley.

Reassemble & set valve clearances; replace valve cover gasket.

Road test then re-inspect for any leakage - all OK.

*Note: Timing belt should be replaced every 60,000 miles or 4 years, whichever is soonest.*

Part Number	Description	Location	QTY
11 14 1 740 845	Timing Cover Gasket		1
11 31 1 469 240	Timing Belt		1
11 31 2 241 090	Tension Roller, Timing		1

### Replace rear brakes.

Estimated Hours: 0.00

Check for pedal feel and brake pull before & after.

Replace rear pads & rotors.

Adjust emergency brake & handbrake.

Part Number	Description	Location	QTY
34 11 1 119 177	Brake Pad		1
34 21 1 152 095	Rotor (Disc), Rear		2
Hydraulic Fluid			1
Envir Disp Fee			2