

GenesisFour Corporation

Estimate: 2542

| | | | | | | | |
|----------------------|------------------------------|-------------------|-------------------|---------------------|----------------------|---------------|----------|
| Name | GenesisFour Truck Service | Contact | AI | Created Time | 03/29/05 10:19 AM | Year | 1998 |
| Address | 123 Main Street | Address 2 | | Advisor | Danno | Make | Kenworth |
| | Anytown, US 00000 | Hat# | | Division | DM | Model | T2000 |
| Home Work Fax | 800-937-4364 978-856-2209 | VN | 1XKTD69X0XJ798135 | PO# | | Lic# | PUU6554 |
| | | EngineData | 16 Liter | Page# | 1 of 1 | Fleet# | 9918 |
| | | | | | | Color | Red |

Job Description

| | | |
|---|-------------------|---------------|
| Coolant Pressure Test | Line Total | 195.00 |
| Top off coolant and install pressure tester | Labor | 195.00 |
| Bring system up to specified pressure | Parts | 0.00 |
| After 15 minutes, inspect system for any loss | Sublets | 0.00 |
| Make minor adjustments | | |
| Report findings to customer | | |

| | | |
|---|-------------------|---------------|
| Replace Right and Left Side Radius Arm Brackets | Line Total | 111.68 |
| Remove and replace componenets and reinstall all related parts. Replaced dust caps for bearings both sides, repack bearings, and replace seals. Tech 104. | Labor | 0.00 |
| | Parts | 111.68 |
| | Sublets | 0.00 |

| Part Number | Description | QTY | Each | Total |
|-------------|--------------------|-----|-------|-------|
| 7-16NYLNU | USS Nylon Lock Nut | 6 | 1.19 | 7.14 |
| 7-16X1U | USS Bolt | 6 | 0.48 | 2.88 |
| E4T238095A | Bracket | 1 | 49.84 | 49.84 |
| E4T23B095B | Bracket Rad/Frm | 1 | 51.82 | 51.82 |

| | | |
|---|-------------------|---------------|
| Replace Right Side Inner & Outer Tie Rod Ends | Line Total | 287.66 |
| Remove and replace componenets and reinstall all related parts. Tech 104. | Labor | 0.00 |
| | Parts | 287.66 |
| | Sublets | 0.00 |

| Part Number | Description | QTY | Each | Total |
|-------------|--------------|-----|--------|--------|
| E7R23049A | Tie Road | 2 | 47.98 | 95.96 |
| E9T23304F | Rod Assembly | 1 | 128.22 | 128.22 |
| F0T23A131A | End Assembly | 1 | 63.48 | 63.48 |

| | | |
|--|-------------------|---------------|
| Repair Rear Door Hinges | Line Total | 390.00 |
| Inspect rear door operation | Labor | 390.00 |
| Replace necessary components to bring back to wrking cndtn | Parts | 0.00 |
| Lubricate all hinges, latches and rollers | Sublets | 0.00 |
| Ensure proper operation of doors | | |

| | | |
|---|-------------------|---------------|
| Perform Three Axle Alignment | Line Total | 487.50 |
| Attach alignment heads to steer axle and rear drive axle. | Labor | 487.50 |
| Set thrust angle on the rear drive axle. | Parts | 0.00 |
| Set caster, camber and toe settings to factory specifications | Sublets | 0.00 |
| Move the heads from the steer axle to the front drive axle | | |
| Set the thrust angle on the front drive | | |
| Adjust steering wheel | | |

| Date | Service Due |
|------------|----------------------|
| 06/28/2005 | PM B Service |
| 03/29/2006 | Three Axle Alignment |

Demo Motors | 123 Main Street | Anytown, US 00000
 Tel: 800-937-4361 | Fax: 978-856-2209 | URL: www.genesisfour.com

Estimates are an approximation of charges to you, and they are based on the anticipated details of the work to be done. It is possible for unexpected complications to cause some deviation from the estimate. If additional parts or labor are required you will be contacted immediately.

| Estimate Total | |
|----------------|-------------------|
| Labor | \$1,072.50 |
| Parts | \$399.34 |
| Sublets | \$0.00 |
| Supplies | \$30.00 |
| Freight | \$25.00 |
| Subtotal | \$1,526.84 |
| Tax | \$0.00 |
| Total | \$1,526.84 |