

GenesisFour Corporation

Estimate: 1124

Name	Danger, Nick	Company		Created	10/22/00	Year	1985
Address	10 Any Street Apt# 10 Detroit, MI 90234	Address 2		Time	2:18 AM 01/27/03	Make	BMW
Home	800-555-1110	End User		Advisor	Adam	Licd for	325I
Work	800-555-1111	Serial #	SDFG2346234762436	Division	DM	Supt Beg	3RDEYE
Fax		Supt End	6CYL	PO#		# Users	16
				Page#	1 of 1	End User	White

Job Description

Replace failed timing belt	Line Total	418.56
Remove valve cover; & inspect valve train. Check cam tensioner & replace if needed. Replace timing belt & pulley. Reassemble & set valve clearances; replace valve cover gasket. Road test then re-inspect for any leakage - all OK. <i>Note: Timing belt should be replaced every 60,000 miles or 4 years, whichever is soonest.</i>		

Part Number	Description	QTY
11 14 1 740 845	Timing Cover Gasket	1
11 31 1 469 240	Timing Belt	1
11 31 2 241 090	Tension Roller, Timing	1

Replace rear brakes.	Line Total	558.60
Check for pedal feel and brake pull before & after. Replace rear pads & rotors; adjust handbrake.		

Part Number	Description	QTY
34 11 1 119 177	Brake Pad	1
34 21 1 152 095	Rotor (Disc), Rear	2
Hydraulic Fluid		1
Envir Disp Fee		2

Oil Service & 10-Point Safety Inspection	Line Total	36.20
Road test to warm engine. Drain & inspect engine oil; report any unusual color or texture. Replace oil filter & oil: use synthetic if synthetic in use already. Check engine coolant level, appearance, & protection; top off. Check battery level; inspect battery terminals; top off. Check belt tensions & report if adjustment needed. Check engine compartment for overall appearance & report. Lube hood hinges & locks. Check steering linkages for wear while draining oil & report. Check exterior lighting; report if any bulbs are inoperative.		

Part Number	Description	QTY
11 12 1 345 223	Oil Filter	1
Oil, QT	Castrol GTX 10W50	4.5

Demo Motors | 123 Main Street | Anytown, US 00000

Tel: 800-937-4361 | Fax: 978-856-2209 | URL: www.genesisfour.com

Estimates are an approximation of charges to you, and they are based on the anticipated details of the work to be done. It is possible for unexpected complications to cause some deviation from the estimate. If additional parts or labor are required you will be contacted immediately.

Estimate Total	
Labor	\$601.50
Parts	\$411.86
Sublets	\$0.00
Supplies	\$24.06
Freight	\$0.00
Subtotal	\$1,037.42
Tax	\$21.27
Total	\$1,058.69